Work Qrde <i>May-01-12 10:3</i> :			*839	993*					-	Page 1
Item ID: Revision ID:	D350-607-511		Accept	*N900	040	100)* ·	Setup Sta	art *N	IS1*
	Quick Release Basket Mounting Ir 01/05/2012 Start Qty: 2.00 15/05/2012 Req'd Qty: 2.00	**		Cust Item II Customer:	D:			Ste	^{ор} *N	IS2*
	Process Plan: 」	Date: 12/05/0	Tooling: SPC (Y/N):	Da	te:]	Run Sta Sto	" [\]	IR1* IR2*
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr									
D350-607-3	A									
*1 \cdots DC Document Control	DOCUMENT CONT Memo Photoco _l	ROL py bluefile & type labels per F	0.00 0.00 PPPD350-607-511 CHG00	2 JB 8 71	ortis		- 7	J 61	MLJ	12-5-15
140	Pick Kit		0.00							
140 Packaging Packaging	Мето		0.00						.	12/05/15
*150 *150*	QC4-100% Inspect k	xits for completeness	0.00	· 						
QC Quality Control	Memo		0.00	lostice			(40)			-

W/O:			V	VORK ORDER CHANGE	S					_
DATE	STEP	PROC	EDURE CH	IANGE	Ву	,	Date	Qty	Approvał Chief Eng / Prod Mgr	Approval QC Inspector
							·		-	
			 							
Part No	•	PAR #:	_ Fault Ca	tegory:	NCR: Y	es N	o DQA	\:	_ Date: _	
	R	esolution:	_ Disposit	ion:	QA: N/C	Clos	sed:		Date:	
NCR:		W	ORK OR	DER NON-CONFORMA	NCE (N	CR)				•
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	Sig	gn & ate	Verific Section		Approval Chief Eng	Approval QC Inspector
	,		Officer Eng	Office Eng		ale				
<u>-</u>										
								*		
							:			
								,		
								i		

Work Orde <i>May-01-12 10:3</i>		993		*839	993*					Page 2
Item ID: Revision ID:	D350-607-5			Accept	*N900	0401	N 0*	Setu	p Start	ומטו
	01/05/2012	Start Qty: 2.00 Req'd Qty: 2.00	*2* *2*		Cust Item I Customer:	ID:			Stop	*NS2*
Approvals:	Process Pla	nn:	Date:	Tooling: SPC (Y/N):		ate:ate:		Run	Start Stop	"NH1"
Sequence ID/ Work Center II 160 *160*)	Operation Description Packaging		Set Up/ Run Hours 0.00	Tool ID	Tool# Pla Co				Reject Insp. Number Stamp
Packaging Packaging		Memo Identify and Location:	pack for shipping as per	0.00 PPP D350-607-511	-			1	,	

170

170

QC

Memo

QC21- Final Inspection - Work Order Release

0.00

0.00

Quality Control

12/5/16 D MF, 2-05-15

Dart Aerospace Ltd

- u	Johann									
W/O:			٧	WORK ORDER	CHANGES					*
DATE	STEP	PRO	CEDURE CI	HANGE		Ву	Date	Qty	Approvat Chief Eng / Prod Mgr	Approval QC Inspector
		,								
									:	
			······································							
Part No	:	PAR #:	Fault Ca	ategory:	NO	CR: Yes	No DQA :	:	* * * * *	-
	R	esolution:	Disposi	tion:	Q.	A: N/C CIG	osed:		Date:	
NCR:		V	VORK OR	DER NON-CON	FORMANC	E (NCR)		or .	
DATE	STEP	Description of NC		Corrective Actio			Verifica	tion	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Des Chief E	cription ng	Sign & Date	Section	ı C	Chief Eng	QC Inspector
		ere en								
									, ,	
,						·		- ,	1.	
				-						e Algori
	·								:	·
	·									
				-					;	•
							:			

Picklist Print May-01-12* 10:35:18 AM Work Order ID: 83993 Parent Item: D350-607-511 Parent Item Name: Quick Release Basket Mounting Installation Comments:

83993 *D350-607-511*

Start Date: 01/05/2012

Required Date: 15/05/2012

Start Qty: 2.00

Required Qty: 2.00

IPP REV:A NEW ISSUE 10-06-28 JLM VERIFIED BY: LL

			-0 3	12111	EMI IEE D I	. 22								
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch		Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3910-3		Manufactu	ıred	No	***************************************		140	Each	12.0000	4	8	~		
D3910-3										**		g B		<u> </u>
					Location	!	Loc	<u>Oty</u>	Loc Code					
					st507			12		_	<u> </u>			
D3984			١,	NI.		81459	140	12	252 1010	_	21122	- J.		
		Manufactu	ired	No			140	f	253.4840	2	4 /			
D3984										**		2B		
Rubber Extrusion, Crosstube					1 Location	. 1.	Loo	04.	I C-1-			0		
. 🖎	مي				ST080	. <i>3</i>	Loc 9	<u>Oty</u> 3.484	Loc Code					
GUII (8) AT 3:00" LONG		ļ				53707		3.484			5370	Ž S	. ,	
D4148-041		Manufactu	red	No			140	Each	0.0000		2 -			
D4148-04 Crosstube Lug Assembly, Fwo	. 1									**	8298	9 JB	50.	· · · · · · · · · · · · · · · · · · ·
D4149-041		Manufactu	red	No			140	Each	8.0000	0	2 v	•		
D4149-04 Crosstube Lug Assembly, Aft	1									**		JB	, the	12/05/
					Location		Loc (<u>Oty</u>	Loc Code					
					ST468			8		_	~			
						81472		2		_	81472	8	٠.	
			4			02077		_						

82966

Dart	Aero	space	Ltd
------	-------------	-------	-----

Dan Ae	rospace	s Liu								•
W/O:			WC	RK ORDER CHA	NGES					
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approvat Chief Eng / Prod Mgr	Approval QC Inspector
	<u> </u>									
Part No	:	PAR #:	Fault Cate	gory:	NCF	R: Yes I	No DQ	A :	Date:	
	R	esolution:	Disposition	n:	QA:	N/C Clo	sed:		Date: _	
NCR:			WORK ORD	R NON-CONFOR	RMANCE	(NCR))			
DATE	STEP	Description of NC	Initial	Corrective Action Action Description	Section B	Sign &	Verific		Approval	Approval
		Section A	Chief Eng	Chief Eng	On	Date	Secti	on C	Chief Eng	QC Inspector
_	ļ				-		1		1	
·										
									ı	
					:					
					,					
								¥-	1	

May-01-12-10;35:18 AM

Work Order ID: 83993

83993

Parent Item:

D350-607-511

D350-607-511

Parent Item Name: Quick Release Basket Mounting Installation

Start Date: 01/05/2012

Required Date: 15/05/2012

Start Qty: 2.00

Required Qty: 2.00

AN4-14A

Purchased

No

140

318.0000

Loc Code

Each

1x121708 &B.S.

Location	<u>L</u>	oc Qty
357		100
121349		100
ST357		218
120187		13
120769		1
121068		17
121243		87
121444		100
	140	Each

Purchased

Purchased

No

No

Location Loc Qty ST300 5520 119075 520 121011 2000 121444 3000

Loc Code

5,520.000

12/011

49F0432P*

Location Loc Qty Loc Code ST275 1022 121255 2

140

121350 121415 1000 20

Each

1,022.000

12/05/15

Dart Aerospace Ltd

		 									
W/O:			V	VORK ORDER CH	ANGES				,	•	
DATE	STEP	PROC	EDURE CH	HANGE		Ву	Date	Qty	Approvat Chief Eng / Prod Mgr	Approval QC Inspector	
									į.		
-			•								
					<u> </u>	•			<u> </u>		
									;		
Part No	:	PAR #:	Fault Ca	ategory:	NC	R: Yes N	lo DQA	·	_ Date:		
	R	esolution:	Disposit	tion:	QA	: N/C Clo	sed:		_ Date: _		
NCR:		W	WORK ORDER NON-CONFORMANCE (NCR)								
DATE	STEP	Description of NC Section A	Initial	Corrective Action Action Descrip	Section B	Sign &	Verific Section		Approval Chief Eng	Approval QC Inspector	
			Chief Eng	Chief Eng		Date	-				
<u></u>				1							
	,				0						
								·	.		
		19 to high			·						
			<u> </u>		:		:				
			:								
					,	,		• .			
					•						
	1		Į			ł					

DART AEROSPACE LTD.

D350-607-3 Page 17 of 19

4.0 WEIGHT AND BALANCE

Installation	Weight	LA	TERAL	LONG	ITUDINAL
		Arm	Moment	Arm	Moment
D350-607-541	80.7 lb	± 49.1 in	± 3962 in-lb	135 in	10895 in-lb
(Standard Basket)	36.6 kg	± 1.25 m	± 45.8 m-kg	3.43 m	125.5 m-kg
D350-607-543	65.7 lb	± 49.1 in	± 3226 in-lb	135 in	8870 in- l b
(Lightweight Basket)	29.8 kg	± 1.25 m	± 37.3 m-kg	3.43 m	102.2 m-kg
D350-607-545	58.7 lb	± 49.1 in	± 2882 in-lb	135 in	7925 in-lb
(Standard Basket)	26.2 kg	± 1.25m	± 32.8 m-kg	3.43 m	89.9 m-kg
D350-607-547	47.7 lb	± 49.1 in	± 2342 in-lb	135 in	6440 in-lb
(Lightweight Basket)	21.6 kg	± 1.25 m	± 27.0 m-kg	3.43 m	74.1 m-kg
D350-607-511 (Quick Release Basket Mounting Kit)	7.2 lb 3.3 kg	± 36.9 in ± 0.94 m	± 266 in-lb ± 3.1 m-kg	135 in 3.43 m	972 in-lb 11.3 m-kg

5.0 PARTS LIST

QTY -541	QTY -543	QTY -545	QTY -547	QTY/ -511	QTY -501	PART NUMBER	DESCRIPTION
X					i	D350-607-541	HELI-UTILITY-BASKET
	Х					D350-607-543	HELI-UTILITY-BASKET
		X				D350-607-545	HELI-UTILITY-BASKET
		•	Х			D350-607-547	HELI-UTILITY-BASKET
1	1	1	1	X		D350-607-511	QUICK RELEASE BASKET MOUNTING KIT
					X	D350-607-501	CONVERSION KIT
1					4	D2690-6	LANYARD
1	11	1	1	-	1		X-TUBE LUG
	4		1	4.741	<u> </u>	D3910-3	EYEBOLT RECEIVER ASSY
1	1	1	1	/ 8	8	D3912-041-7 D3984-030	RUBBER EXTRUSION, X-TUBE
<u> </u>				/ 8	-8		LONG BASKET ASSY
1						D4030-041	LONG BASKET ASSY, LIGHTWEIGHT
	1					D4030-043	SHORT BASKET ASSY
		1				D4032-041	SHORT BASKET ASSY, LIGHTWEIGHT
- 4			1			D4032-043	PLACARD-INSTRUCTIONS
1	1	1	1	ļ	1	D4085-3	
1				ļ	1	D4086-200	PLACARD, MAX LOAD
	1			<u> </u>	1	D4086-215	PLACARD, MAX LOAD
		1		ļ	1	D4086-220	PLACARD, MAX LOAD
			1		1	D4086-232	PLACARD, MAX LOAD
				/ 1	1	D4148-041	FWD X-TUBE LUG ASSY
L.,				71_	1	D4149-041	AFT X-TUBE LUG ASSY
1	1	1	1		1	D4150-041	ATTACHMENT ARM ASSY
1	1	1			1	D4151-041	BASKET FWD HARDPOINT ASSY (LOWER)
1	1	1	1		1	D4151-043	BASKET FWD HARDPOINT ASSY (UPPER)
6	6	6	6		6	AN4-13A	BOLT
	<u> </u>			∠ 16	. 16	*AN4-14A	BOLT
1	1	1	1	-	1	AN4C15	BOLT
1	1	1	1		1	AN310C4	CASTELLATED NUT
1	1	1			1	MS17984-C413	QUICK RELEASE PIN
6	6	6	6	/16	22.	MS21042L4	NUT (OR MS21042-4)
1	1	1	1		1	MS24665-151	COTTER PIN
2	2	2	2		2	NAS1515H4L	WASHER
12	12	12	12	-32	-44-	NAS1149F0432P	WASHER
3	3	3	3		3	NAS1149C0463R	WASHER

• COPYRIGHT © 2019 BY DART AEROSPACE LTD •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: A

Date: 10.06.28